

Certificate of Verification

Certificate Number:

20250317-MH59905

Report Reference:

MH59905-20201209

Issue Date:

2024-12-09

Expiration Date:

2026-12-09



Issued to:

FireService Management LLC

32001 Schoolcraft

Livonia, MI 48156

This certificate confirms that the above service provider has been verified to perform the following services:

Verified Independent Service Provider (ISP)

Service	Included
Advanced Cleaning and Sanitization	Yes
Advanced Inspection	Yes
Advanced Repairs	Yes

And has been evaluated by UL LLC in accordance with the following Standard:

NFPA 1851, Standard on Selection, Care, and Maintenance of Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of UL LLC is the only method provided by UL to identify service providers and organizations verified under its Certificate and Follow-Up Service. Service providers and organizations for which Certificates are issued are considered by UL to be compliant with the applicable requirements at the time of issuance. UL assumes no liability for any loss that may result from nonconformity with requirements.

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

Certificate of Verification

Certificate Number: 20250317-MH59905
Report Reference: MH59905-20201209
Issue Date: 2024-12-09
Expiration Date: 2026-12-09

Service location			
Mobile facility:	<input type="checkbox"/> Yes, mobile facility ID: N/A <input checked="" type="checkbox"/> No		
Service performed by:	Advanced cleaning and Sanitization	Advanced inspection	Advanced repairs
Mobile facility	-	-	-
Physical location	X	X	X

General repair			
Outer shell repairs:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Thermal barrier repairs:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Moisture barrier repairs:	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Moisture barrier materials eligible for repair			
Manufacturer	Model	Tape	Seam Type
W.L. Gore and Associates	CROSSTECH Black, 2F	10880780/10880782	Felled & overedge
	GORE RT 7100, 3D		
Stedfast	Stedair 3000	TX-1202	
	Stedair 4000		

Issued by:



Karla S. Litaker
Staff Chemist

Reviewed by:



Amanda H. Newsom
Principal Engineer



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.